



# 15<sup>th</sup> fToA bin


From last time:



No noticeable change in length of bin 0, thus indicating a change in the control voltage as the culprit for not filling bin 15



# Triggers from testbeam



There seems to be an increase in triggers at an integer number times 83kHz?